

## RECEIVING INSPECTION REPORT

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080020-1

2961 E. COLORADO ST., PASADENA, CALIF.

RECEIVED FROM

DATE REC'D. 2-11-59

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	S.O. NO.
	10	322		036	0	10				
DRAWING NO. AND DESCRIPTION										
73730-A Link										
#ipper #35925										
QUANTITY										
ACCEPTED 10 ✓										
REJECTED										
REMARKS										
W.L. K... H.E. K...										

RECEIVED  
BYINSPECTED  
BY

DATE 2-11-59

REMARKS RETURNED

## RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11242

RECEIVED FROM

DATE REC'D. 2-11-59

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	S.O. NO.
	3	322		64	0	10				
DRAWING NO. AND DESCRIPTION										
72196 "B" Fitting										
#ipper #35919										
QUANTITY										
ACCEPTED 3 ✓										
REJECTED										
REMARKS										
W.L. K... H.E. K...										

RECEIVED  
BYINSPECTED  
BY

DATE

REMARKS RETURNED

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080020-1